

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

05/13/2020

Submitted Date:

05/15/2020

Document Number:

690101863

**FIELD INSPECTION FORM**
 Loc ID 331092 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL &amp; GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

2 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
		cogccinspections@anadarko.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258437	WELL	SI	02/01/2020	OW	123-20139	HSR-SHUTT FEDERAL 1-18 A	SI
453324	TANK BATTERY	AC	12/07/2017		-	Shutt Federal 1-18A battery	EG

**General Comment:**
 Engineering Integrity; Flowline Inspection.  
 Photos Uploaded.

**Inspected Facilities**Facility ID: 258437 Type: WELL API Number: 123-20139 Status: SI Insp. Status: SIFacility ID: 453324 Type: TANK API Number: - Status: AC Insp. Status: EG**Flowline**#1 Type: Non-Well Site of LinesFlowline DescriptionFlowline Type: Non-Well Site Size: Material:

Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:

Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☒ 1103. Abandonment

Comment: Well is shut in (HSR Shutt Federal 1-18A); scheduled to be plugged and abandoned. The off location flowline is shut in at wellhead (OOSLAT applied). Off location flowline is shut in at facility/ inlet to heated horizontal separator (OOSLAT applied). Second well previously serviced by facility (Shutt Federal #18-8) has been plugged and abandoned; COGCC form 6 subsequent Doc #402082239 filed on 06/25/2019. Form 42 notice of flowlines abandoned per 1105 Doc #402091852 received on 06/28/2019. No corrective actions were identified during this field inspection.

Corrective Action:

Date:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
690101867	Signage at facility/ battery	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5152214">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5152214</a>
690101869	Flowline shut in; OOSLAT in place	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5152215">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5152215</a>