

Impetro Resources LLC, Marick 1-A
121-08461

Inspection #688307856

5/13/2020

Pit Inspection



Colorado Oil and Gas Conservation Commission
39.80942, -103.19391, 4744.1ft, 69°
05/13/2020 12:05:09 PM



Colorado Oil and Gas Conservation Commission
39.80927, -103.19445, 4731.0ft, 219°
05/13/2020 12:04:37 PM



Colorado Oil and Gas Conservation Commission
39.80925, -103.19453, 4750.7ft, 313°
05/13/2020 12:02:55 PM



Colorado Oil and Gas Conservation Commission

39.80911, -103.19464, 4750.7ft, 43°

05/13/2020 12:02:17 PM



Colorado Oil and Gas Conservation Commission
39.80877, -103.19386, 4727.7ft, 59°
05/13/2020 11:55:54 AM



Colorado Oil and Gas Conservation Commission
39.8089, -103.19418, 4665.4ft, 101°
05/13/2020 11:55:38 AM



Colorado Oil and Gas Conservation Commission
39.80876, -103.19376, 4747.4ft, 33°
05/13/2020 11:56:05 AM



Colorado Oil and Gas Conservation Commission
39.80818, -103.1937, 4744.1ft, 227°
05/13/2020 11:57:38 AM



Colorado Oil and Gas Conservation Commission
39.80819, -103.1937, 4740.8ft, 134°
05/13/2020 11:57:42 AM



Colorado Oil and Gas Conservation Commission
39.80819, -103.19369, 4740.8ft, 165°
05/13/2020 11:57:44 AM



Colorado Oil and Gas Conservation Commission
39.80816, -103.19458, 4740.8ft, 266°
05/13/2020 11:59:36 AM



Colorado Oil and Gas Conservation Commission

39.80818, -103.19461, 4747.4ft, 318°

05/13/2020 11:59:44 AM



Colorado Oil and Gas Conservation Commission

39.80855, -103.19469, 4750.7ft, 315°

05/13/2020 12:00:36 PM



Colorado Oil and Gas Conservation Commission

39.80964, -103.19398, 4750.7ft, 257°

05/13/2020 12:11:56 PM



Colorado Oil and Gas Conservation Commission
39.8096, -103.19371, 4734.3ft, 159°
05/13/2020 12:12:46 PM