





40.09917, -108.81568, 5143.5ft, 312°
05/15/2020 02:13:29 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Pump jack.

Stagner 7 API: 05-103-07280
Inspection: 700401505



40.0992, -108.81572, 5137.5ft, 352°
05/15/2020 02:13:45 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Stained soil.

Stagner 7 API: 05-103-07280
Inspection: 700401505



