



40.09842, -108.81603, 5145.4ft, 353°
05/15/2020 02:20:37 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 1. Location.

Stagner 6 API: 05-103-07362
Inspection: 700401509



40.09895, -108.81592, 5139.0ft, 305°
05/15/2020 02:15:14 PM



40.09901, -108.81593, 5150.6ft, 268°
05/15/2020 02:16:12 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

**Photo 3. Unused equipment. Pump jack from
Stagner 2.**

Stagner 6 API: 05-103-07362
Inspection: 700401509





40.09906, -108.81607, 5139.7ft, 257°
05/15/2020 02:16:29 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 5. Unused equipment (Stagner2 ?)

Stagner 6 API: 05-103-07362
Inspection: 700401509



40.09897, -108.81616, 5137.2ft, 291°
05/15/2020 02:16:48 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 7. Well head.

Stagner 6 API: 05-103-07362
Inspection: 700401509



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 8. Well head.

Stagner 6 API: 05-103-07362
Inspection: 700401509

