

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/15/2020

Submitted Date:

05/17/2020

Document Number:

700401505

**FIELD INSPECTION FORM**

Loc ID 336550 Inspector Name: Moran, Rick On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10342  
Name of Operator: WOODARD\* SANDRA K  
Address: 602 OURAY AVENUE  
City: GRAND JUNCTION State: CO Zip: 81501

**Findings:**

- 7 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
Burger, Craig		craig.burger@state.co.us	
,	970-261-6589	3oilwells@gmail.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229623	WELL	SI	06/01/2019	OW	103-07280	STAGNER RECTOR 7	SI

**General Comment:**

On 5-15-2020 inspector Rick Moran conducted a follow up inspection at Woodard Sandra K well Stagner 7 in Rio Blanco county of FIR documents:

- 1) 679705374 dated 9-6-2019.
- 2) 700400162 dated 2-24-2020.

The following compliance issues are uncompleted:

- 1) Stained & oily soil around pump jack. Photo 3 Complete by 10-9-2019.
- 2) Open bucket of fluid next to well head. Photo 3. Complete by 10-9-2019.

This is a summary of inspection report 700401505.

**Location**

Overall Good:

**Signs/Marker:**

	Type WELLHEAD		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	911		
Corrective Action:		Date:	

**Good Housekeeping:**

Type	OTHER		
Comment:	Open bucket of fluid next to well head. Bucket without wildlife protection & could be tipped over.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.	Date:	10/09/2019
Type	OTHER		
Comment:	Stained soil around well head and flow line.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.	Date:	10/09/2019

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

					corrective date
Type: Pump Jack	# 1				
Comment:					
Corrective Action:		Date:			

**Venting:**

Yes/No	YES		
Comment:	Casing open to atmosphere. A gas odor was detected & infrared movies were recorded during this inspection of the gas venting. During inspection 679705374 a 3 cubic ft bag filled in 12 minutes with gas.  Well located 800 ft from the nearest residence.		
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 229623 Type: WELL API Number: 103-07280 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass					

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

