

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/15/2020

Submitted Date:

05/17/2020

Document Number:

700401513**FIELD INSPECTION FORM**Loc ID 333342 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10342Name of Operator: WOODARD* SANDRA KAddress: 602 OURAY AVENUECity: GRAND JUNCTION State: CO Zip: 81501**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
Burger, Craig		craig.burger@state.co.us	
,	970-261-6589	3oilwells@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229445	WELL	SI	06/01/2019	OW	103-07101	STAGNER 2	TA

General Comment:

On 5-15-2020 inspector Rick Moran conducted a routine inspection at Woodard Sandra K well Stagner 2 in Rio Blanco county.

The following compliance issues were observed:

- 1) Open bucket of oil at well head. Photos 3 & 4. Complete by 6-17-2020.
- 2) Current MIT needed for this temporarily abandon well.

This is a summary of inspection report 700401513.

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Open bucket of oil at well head.		
Corrective Action:	Comply with Rule 603.f .	Date:	06/17/2020

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	400 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition Adequate

Other (Content)

Other (Capacity)

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate			Adequate
Comment:				

Corrective Action:		Date:	
Venting:			
Yes/No	YES		
Comment:	Casing open to atmosphere. A gas odor was detected & infrared movies were recorded during this inspection of the gas venting. Durng inspection 679705372 Stagner 2 filled a 3 cubic ft bag in 7 minutes. Well located 800 ft from the nearest residence.		
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 229445 Type: WELL API Number: 103-07101 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: Last recorded production May 2019. No pump jack present at well head.

No current MIT on record or delinquent as required by Rule 326.

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass					

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Optical Gas Imaging SurveySurvey Type: RoutineCurrent Operations: ☐ Production ☐ Workover ☐ Flowback ☐ Referred to APCD

GPS(entrance of location): Lat: _____ Long: _____

Wind: Light Speed: _____ (mph) Direction From: _____ Weather: Partly Temperature: (F)

Assisting Staff: _____ Camera #: _____

☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
2:45	PM	3:00	PM	Wellhead(s)

Comment: FLIR camera used to image casing gas venting.

Corrective Action: _____ Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700401514	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5152338
700401515	HSM infrared movie of gas	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5152339
700401516	Infrared movie of gas	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5152340