

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/14/2020

Submitted Date:

05/18/2020

Document Number:

688800731

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Hughes, Jim On-Site Inspection 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

1 Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Heil, John		john.heil@state.co.us	
Murray, Richard		g.richard.murray@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
476429	SPILL OR RELEASE	AC	05/15/2020		-	Dry Creek Water Transfer Line	EI

General Comment:

On May 14, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Spill/Release Point ID #476429. For more information regarding this release, please refer to Initial Spill/Release Report Document #402399028. COGCC Western Integrity Inspector Richard Murray was on site during this inspection.

Inspected Facilities

Facility ID: 476429 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental**Spills/Releases:**Type of Spill: PRODUCED WATEREstimated Spill Volume: 15Comment: [For more information regarding this release, please refer to Initial Spill/Release Report Document #402399028.](#)Corrective Action: [Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.](#)Date: 06/18/2020Reportable: YESGPS: Lat 37.223070Long -107.678280Proximity to Surface Water: 70Depth to Ground Water: 30**Water Well Complaint:**

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

COGCC Comments

Comment	User	Date
<p>On May 14, 2020 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Spill/Release Point ID #476429. For more information regarding this release, please refer to Initial Spill/Release Report Document #402399028. COGCC Western Integrity Inspector Richard Murray was on site during this inspection, as well as BP and Crossfire representatives.</p> <p>During this inspection and open excavation was observed with wet and stained soil in the base. A hydrovac truck had been excavating impacted material from the bottom of the excavation. The release point was a fiberglass gathering line that was in the process of being abandoned. The release appeared to have been fully contained within the excavation.</p>	hughesjo	05/18/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800735	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5153387