

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/18/2020

Submitted Date:

05/18/2020

Document Number:

700700718**FIELD INSPECTION FORM**

Loc ID 420296	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: <u>10531</u> Name of Operator: <u>GRIZZLY OPERATING LLC</u> Address: <u>5847 SAN FELIPE #3000</u> City: <u>HOUSTON</u> State: <u>TX</u> Zip: <u>77057</u>				Findings: <u>17</u> Number of Comments <u>2</u> Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Grizzly		scollett@grizzlyenergyllc.com	
, Grizzly		aaxelson@grizzlyenergyllc.com	
, Grizzly		sghan@grizzlyenergyllc.com	SR. EH&S

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
420317	WELL	PR	04/18/2012	GW	045-20119	CBS 31C-21-692	PR
420318	WELL	PR	03/23/2012	GW	045-20120	CBS 32B-21-692	PR
420319	WELL	PR	04/18/2012	GW	045-20121	CBS 41C-21-692	PR
420320	WELL	PR	04/18/2012	GW	045-20122	CBS 31B-21-692	PR
420321	WELL	PR	04/18/2012	GW	045-20123	CBS 41D-21-692	PR
420322	WELL	PR	03/22/2012	GW	045-20124	CBS 41B-21-692	PR
420323	WELL	PR	04/18/2012	GW	045-20125	CBS 31D-21-692	PR
420324	WELL	PR	03/23/2012	GW	045-20126	CBS 42D-21-692	PR
420325	WELL	PR	03/22/2012	GW	045-20127	CBS 32D-21-692	PR
420326	WELL	PR	03/23/2012	GW	045-20128	CBS 42B-21-692	PR

General Comment:

COGCC Inspection Report Summary

On Monday 5/18/2020 at approximately 11:30 AM, I, Inspector Scott Ramsey, conducted a routine inspection at Grizzly CBS, at Location # 420296 in Garfield Colorado.

While there, I observed normal production operations. Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

During this inspection the following possible compliance issues were observed:

- Two unmarked dead men.
- Chemical tank containment is not capable of holding 110%.
- Debris around tank battery.
- Master valve is leaking.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Chemical tank containment is not capable of holding 110%, Debris around tank battery and Master valve is leaking. see photos		
Corrective Action:	provide 110% containment under chemical tank, remove debris and repair leaking master valve.	Date:	06/08/2020

Overall Good: ☐**Spills:**

Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				

Fencing/:

Type	IGNITOR/COMBUSTOR		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			

Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 10		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 10		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	chemical tank and 500 gallon methanol tank		
Corrective Action:		Date:	
Type: Deadman # & Marked	# 7		
Comment:	Two (2) are unmarked		
Corrective Action:	remove or mark dead men	Date:	06/08/2020
Type: Plunger Lift	# 10		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	6	500 BBLS	HEATED STEEL AST		,
Comment:	two (2) tanks are not heated				
Corrective Action:				Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:			Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type	Ignitor/Combustor	
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	420317	Type:	WELL	API Number:	045-20119	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	420318	Type:	WELL	API Number:	045-20120	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	420319	Type:	WELL	API Number:	045-20121	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	420320	Type:	WELL	API Number:	045-20122	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	420321	Type:	WELL	API Number:	045-20123	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	420322	Type:	WELL	API Number:	045-20124	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	420323	Type:	WELL	API Number:	045-20125	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			
Facility ID:	420324	Type:	WELL	API Number:	045-20126	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:						Date:			

Facility ID:	420325	Type:	WELL	API Number:	045-20127	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Facility ID:	420326	Type:	WELL	API Number:	045-20128	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment: producing

Corrective Action:

Date:

Environmental	
Spill/Remediation:	
Comment:	
Corrective Action:	<div></div> <div>Date: </div>
Emission Control Burner (ECB): YES	
Comment:	
Pilot: ON	Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches		Culverts				
		Gravel				
Gravel		Ditches				
Berms		Check Dams				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700700723	photos for CBS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5153501