

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/18/2020

Submitted Date:

05/19/2020

Document Number:

700401539

FIELD INSPECTION FORM

Loc ID 315190 Inspector Name: Moran, Rick On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10112
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC
Address: 5057 KELLER SPRINGS RD STE 650
City: ADDISON State: TX Zip: 75001

Findings:

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------------|--------------|---------------------------------|------------|
| Kellerby, Shaun | 970-712-1248 | shaun.kellerby@state.co.us | |
| Trujillo, Aaron | | aaron.trujillo@state.co.us | |
| Energy, Foundation | | regulatory@foundationenergy.com | Regulatory |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------|-------------|
| 230387 | WELL | PA | 12/10/2015 | GW | 103-08049 | TAIGA FED 3L-20-4-102 | PA |

General Comment:

On 5-18-2020 inspector Rick Moran conducted a routine inspection at Foundation Energy Managment well Taiga Fed 3L-20-4-102 in Rio Blanco county.

The following compliance issues were observed:
1) Unused equipment - flow line risers, 8 deadman, concrete rails & short pipes. Photos 2, 3, 4. Complete by 8-15-2020.

This is a summary of inspection report 700401539.

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type: UNUSED EQUIPMENT

Comment:

Corrective Action:

Date: 08/15/2020

Overall Good:

Spills:

| Type | Area | Volume | | | |
|------|------|--------|--|--|--|
| | | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type: Deadman # & Marked

Comment:

Corrective Action:

Date:

Type: Flow Line

Comment:

Corrective Action:

Date:

Venting:

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type:

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 230387 Type: WELL API Number: 103-08049 Status: PA Insp. Status: PA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Other | Pass | | | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 700401540 | inspection photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5154091 |