

**Inspection Photos**  
**Location Name: Krajack 43-27 #2**  
**API: 05-067-08835**



**Krajack 43-27 #2 production equipment.**



**Krajack 43-27 #2 well head.**

**Inspection Photos**  
**Location Name: Krajack 43-27 #2**  
**API: 05-067-08835**



**Weeds present within secondary containment ring. Paint is peeling off of PBV.**



**Stained soil near well head.**