

Inspection Photos

API: 071-07710

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 5/18/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07710 | Date: 5/18/2020

Inspection Photos



Photo 1. Facing north near the Valent Canyon location. There is an erosion channel forming along this area of the road. Lat/Long:37.34363,-104.60370.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07710 | Date: 5/18/2020

Inspection Photos



Photo 2. Facing northeast along the access road. The access road has not been reclaimed and culverts remain in the drainage.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07710 | Date: 5/18/2020

Inspection Photos



Photo 3. Facing north along the access road. It appears during precipitation events stormwater has previously flowed across the road in area of the red arrow. This has caused rip/rap to be displaced on other side shown in next photo.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07710 | Date: 5/18/2020

Inspection Photos



Photo 4. It appears rock rip/rap was displaced from this area of the embankment which could possibly cause erosion to occur in this area if stormwater flows across this embankment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07710 | Date: 5/18/2020

Inspection Photos



Photo 5. Facing toward the culvert outlet in the drainage shown in previous photos.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07710 | Date: 5/18/2020

Inspection Photos



Photo 6. Facing east along the access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07710 | Date: 5/18/2020

Inspection Photos



Photo 7. Facing east toward the location. Two fence post remain at the location and need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07710 | Date: 5/18/2020

Inspection Photos



Photo 8. Facing northeast at the east side of the location. This area consist primarily of weeds (Redstem filaree).



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07710 | Date: 5/18/2020

Inspection Photos




Photo 9. Facing southwest at the east side of the location. This area consist primarily of weeds (Redstem filaree). 100 ft. tape measure shows area that consists of weeds.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos



Photo 10. Facing toward the pit that remains per approved variance request.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07710 | Date: 5/18/2020

Inspection Photos



Photo 11. Facing southwest toward the location and pit area. This area of the pit berm is bare of vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07710 | Date: 5/18/2020

Inspection Photos



Photo 12. There were 3 metal H-braces found at the location that were apart of the location fence. These H-braces need to be removed from the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07710 | Date: 5/18/2020

Inspection Photos



Photo 10. Facing west toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07710 | Date: 5/18/2020