

Inspection Photos
Operator: Southland Royalty
API#: 007-06222
Date: 5/15/2020



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward. Revegetation is progressing on the fill slope with grasses such as western wheatgrass, crested wheatgrass, and Indian ricegrass.




Photo 3. View of erosional rilling where concentrated stormwater flows off of the well pad. Russian thistle debris is also present.



Photo 4. View of erosional channel approximately 1.5 feet wide and 1 foot deep, where stormwater flows exiting the southern well pad become concentrated and channeling off of the project area.



Photo 5. View of reference area vegetation comprised of pinyon juniper woodland with understory of grasses and forbs such as Indian ricegrass, James galleta, and Navajo tea.