

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/19/2020

Submitted Date:

05/19/2020

Document Number:

699301759**FIELD INSPECTION FORM**Loc ID 336468 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|-------|--------------------------|---------------------------------|
| , | | cogccinspection@pdce.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 261330 | WELL | SI | 06/01/2018 | GW | 123-20584 | WALSH 23-24 | SI |

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

| | | | | | |
|------|------|--------|--|--|--|
| | | | | | |
| Type | Area | Volume | | | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected Facilities

Facility ID: 261330 Type: WELL API Number: 123-20584 Status: SI Insp. Status: SI

CementCement ContractorContractor Name: Nextier

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging OperationsDepth Plugs(feet range): 1650-1354Cement Volume (sx): 105 sxsGood Return During Job: YESCement Type: 3

Comment: Watched Nextier Cement crew mix and pump the stub plug with 105 SXS 15.8 # type 3 Cement from 1650' to 1354' with good returns. Ensign Rig crew POOH to 868', attach Cement head, Nextier Cement crew mix and pump 208 SXS 15.8 # type 3 cement to surface with good returns.

Corrective Action: _____

Date: _____

COGCC Comments

| Comment | User | Date |
|--|--------|------------|
| <p>COGCC Inspection Report Summary</p> <p>On Tuesday 5-19-2020 at approximately 1430 hrs to 1730 hrs I, Inspector Robbie Revas, Conducted an on-site P & A inspection at a PDC location:</p> <p>Walsh 23-24 at API #05-123-20584 in Weld County Colorado.</p> <p>While there, I observed a Plug and Abandon Job.</p> <p>Form 42 (PA) Doc # 402397707 was submitted on 5-13-2020 and is approved.</p> <p>Form 6 (N)WAR Doc # 402394095 was submitted on 5-8-2020 and is approved.</p> <p>Watched Nextier Cement crew mix and pump the stub plug with 105 SXS 15.8 # type 3 Cement from 1650' to 1354' with good returns. Ensign Rig crew POOH to 868', attach Cement head, Nextier Cement crew mix and pump 287 SXS 15.8 # type 3 cement to surface with good returns TOOH with tubing, let stabilize then pumped down 6 sxs 15.8 # type 3 cement to top off. Cement crew RDMO Workover crew RD and will MO in the AM.</p> <p>Casing Cut off crew scheduled for tomorrow.</p> <p>During this inspection no compliance issues were observed:</p> <p>See attached photos.</p> <p>Location is dry, weather is clear.</p> <p>I was speaking with Bud Holman Company representative for PDC during P & A operations.</p> <p>No follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>Continuing education COGCC Inspection Report Summary.</p> <p>This is a summary of inspection report.</p> | revasr | 05/19/2020 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 699301760 | loc pics | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5154709 |

| |
|--|
| |
|--|