

Inspection Photos

Location Name: CAERUS PICEANCE LLC Keinath Federal /9-12H2 (C10OU)

Location ID: 334093



Photo #1213 from NW corner of location.



Photo #1214 Multiple unused pieces of pipe in tank containment.

Inspection Photos

Location Name: CAERUS PICEANCE LLC Keinath Federal /9-12H2 (C100U)

Location ID: 334093



Photo #1215 Multiple unused pieces of pipe in tank containment.



Photo #1216 Stained gravel inside tank containment.

Inspection Photos

Location Name: CAERUS PICEANCE LLC Keinath Federal /9-12H2 (C100U)

Location ID: 334093



Photo #1217 Flow line riser not LO/TO.