

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/14/2020

Submitted Date:

05/20/2020

Document Number:

693200661

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Murray, Richard On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Operator Information:
OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 1199 MAIN AVENUE SUITE 101
City: DURANGO State: CO Zip: 81301

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------------|-------|-------------------------------|----------------------------------|
| Hughes, Jim | | jimo.hughes@state.co.us | |
| Inspections, All | | SanJuanCOGCC@bp.com | All Inspections |
| Schlagenhauf, Mark | | mark.schlagenhauf@state.co.us | Engineering Integrity Supervisor |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------------------|--------|-------------|------------|---------|-------------------------------|-------------|
| 476429 | SPILL OR RELEASE | AC | 05/15/2020 | | - | Dry Creek Water Transfer Line | EG |

General Comment:

Dry Creek Pipeline Realignment and Abandonment Project

Engineering Integrity Inspection performed on May 14, 2020. To witness plug and abandon and realign of Flowlines in CODOT right-of-way Highway 160

During the purging activities of 6" flowline abandonment, approximately 15 bbls of produced water overflowed the secondary containment catchment and flowed into the opened pipeline excavation.

SW EPS Jim Huges was on location to perform an environmental field inspection.

For more information regarding this release, refer to Initial Spill/Release Report Document #402399028 and Inspection Document #688800731

Inspected Facilities

Facility ID: 476429 Type: SPILL OR API Number: - Status: AC Insp. Status: EG

Flowline

#1 Type: Non-Well Site 1 of Lines

Flowline Description

Flowline Type: Non-Well Site Size: 6" Material: Fiberglass
Variance: Age: 5-10 Yrs Contents: Produced Water

Integrity Summary

Failures: Other Spills: Yes Repairs Made: No
Coatings: No H2S: No Cathodic Protection: No

Pressure Testing

Witnessed: No Test Result: Pass Charted: Yes

COGCC Rules(check all that apply)

 1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. AbandonmentComment: 6" fiberglass produced water gathering flowline was plugged and abandoned in place then realigned with 6" carbon steel flowline in CDOT right-of-way. Flowline was purged and piggedNew 10" and 6" Flowline were manifold together for one pressure tested. Pressure test was for 8 hours at 1000psi with no leak off

Corrective Action:

Date:

#2 Type: Sales Line 1 of Lines

Flowline Description

Flowline Type: Sales Line Size: 10" Material: Carbon Steel
Variance: No Age: 5-10 Yrs Contents: Natural Gas

Integrity Summary

Failures: Spills: Repairs Made:
Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: No Test Result: Pass Charted: Yes

COGCC Rules(check all that apply)

 1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. AbandonmentComment: 10" Carbon steel gas gathering flowline was plugged and abandoned in place then realigned with 10" carbon steel flowline in CDOT right-of-way. Flowline was purged and piggedNew 10" and 6" Flowline were manifold together for one pressure tested. Pressure test was for 8 hours at 1000psi with no leak off

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 693200662 | Photo log | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5155659 |