



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	adequate		
Corrective Action:			Date:
Type	BATTERY		
Comment:	adequate		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:			Date:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Stained soil under load out line on east crude oil tank		
Corrective Action:	Comply with Rule 907.e		Date: 06/04/2020

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	fabricated square tubing		
Corrective Action:			Date:

**Equipment:**

Type: Bradenhead	# 1		corrective date
Comment:	Appears to be plumbed to surface		
Corrective Action:			Date:
Type: Vertical Separator	#		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:

Type: Horizontal Heated Separator	# 1	
Comment:	bird protector has fallen off and is lying next to separator	
Corrective Action:	Comply with Rule 605.b (7)	Date: 06/20/2020

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 239920 Type: WELL API Number: 123-07708 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary                      On Wednesday 5/20/2020 at approximately 1415 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kauffman location.</p> <p style="text-align: center;">Vonasek # 1 at API #05-123-07708</p> <p>in Weld County Colorado.                      While there, I observed a producing wellsite and tank battery.                      During this inspection the following possible compliance issues were observed:                      907.e housekeeping: Stained soil at load out line on the East Crude oil tank, CA date 6-4-2020                      See attached photos 4 &amp; 5.                      605.b(7) wild life screen: Bird protector has fallen off of Horizontal Heated Separator stack and is lying on the ground, CA date 6-20-2020 see attached photos 6 &amp; 8.                      Location is dry, weather is clear.                      A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.                      Continuing education COGCC Inspection Report Summary.                      This is a summary of inspection report.</p>	revasr	05/20/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699301774	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5155866">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5155866</a>