

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/06/2020

Submitted Date:

05/14/2020

Document Number:

688000449

**FIELD INSPECTION FORM**

Loc ID 311869 Inspector Name: YOUNG, ROB On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 94300  
Name of Operator: WARD & SON\* ALFRED  
Address: P O BOX 737  
City: OGALLALLA State: NE Zip: 69153

**Findings:**

- 3 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Ward, Randy	(308) 280-0100	randy@wardoil.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
107663	PIT	AC			-	COLORADO "B"	EI

**General Comment:**

Environmental inspection related to Rem #8073, Former oil skim pit remediation. Impacted soil stockpile remains on site and is accumulating impacted soil from other locations. Remove and properly dispose the soil stockpile immediately.

**Inspected Facilities**

Facility ID: 107663 Type: PIT API Number: - Status: AC Insp. Status: EI

**Environmental**

**Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)	
Oily Soil	Piles	Inadequate			
Comment	Impacted soil stockpile remains on location east of the open pit remediation. Soil stockpile requires immediate off site disposal at a commercial landfill.				
Corrective Action	Immediately remove the impacted soil stockpile and transport to a commercial landfill for proper disposal per Rule 907.e. and 907.b.(1). CA date from 3/29/2019 FI 688000305 (5/24/2019) remains in effect.			Date:	05/24/2019

**Spill/Remediation:**

Comment:	Oil impacted soil has not been laterally defined in the open excavation. It is likely that the vertical separator will require removal/relocation to allow for adequate excavation to the north and along the east side of the excavation.		
Corrective Action:	Submit an eForm 27 outlining plans to adequately assess and or remediate oil impacted soils in the excavation to allow for project closure.	Date:	05/29/2020

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_ Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402399057	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5151234">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5151234</a>
688000450	Location photographs	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5151213">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5151213</a>