

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/21/2020

Submitted Date:

05/21/2020

Document Number:

699101757

**FIELD INSPECTION FORM**

Loc ID 302908 Inspector Name: Burns, Adam On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1001 NOBLE ENERGY WAY  
City: HOUSTON State: TX Zip: 77070

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name | Phone | Email                                  | Comment                         |
|--------------|-------|--|---------------------------------|
|              |       | NBL_DJBU_Inspections@NB<br>LENERGY.COM | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 301330      | WELL | PR     | 08/05/2011  | OW         | 123-30003 | ABBEY D 01-23 | PR          |

**General Comment:**

*(This area is intentionally left blank for general comments.)*

**Location**

Overall Good:

**Signs/Marker:**

|                    |               |       |  |
|--------------------|---------------|-------|--|
|                    | Type WELLHEAD |       |  |
| Comment:           |               |       |  |
| Corrective Action: |               | Date: |  |

Emergency Contact Number:

|                    |          |       |       |
|--------------------|----------|-------|-------|
| Comment:           | Adequate |       |       |
| Corrective Action: |          | Date: | _____ |

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |  |
|------|------|--------|--|--|--|
|      |      |        |  |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

|                    |               |       |  |
|--------------------|---------------|-------|--|
|                    | Type WELLHEAD |       |  |
| Comment:           | Panel         |       |  |
| Corrective Action: |               | Date: |  |

**Equipment:**

|                    |                                   |       |  |  |                 |
|--------------------|-----------------------------------|-------|--|--|-----------------|
|                    |                                   |       |  |  | corrective date |
| Type: Bradenhead   | # 1                               |       |  |  |                 |
| Comment:           | Appears to be plumbed to surface. |       |  |  |                 |
| Corrective Action: |                                   | Date: |  |  |                 |
| Type: Plunger Lift | # 1                               |       |  |  |                 |
| Comment:           |                                   |       |  |  |                 |
| Corrective Action: |                                   | Date: |  |  |                 |

**Venting:**

|                    |    |       |  |
|--------------------|----|-------|--|
| Yes/No             | NO |       |  |
| Comment:           |    |       |  |
| Corrective Action: |    | Date: |  |

**Flaring:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Inspected Facilities**

Facility ID: 301330 Type: WELL API Number: 123-30003 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**COGCC Comments**

| Comment  | User   | Date       |
|--|--------|------------|
| <p><a href="#">COGCC Inspection Report Summary</a><br/>                     On Thursday 5/21/20 at approximately 1245hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Abby D 1-23 of Noble Energy at Location ID: 302908 in Weld County, Colorado.<br/>                     While there, I observed a production well that is producing<br/>                     No violation of the COGCC rules were observed at the time of inspection.<br/>                     This is a summary of inspection report.<br/>                     Continuing education inspections</p> | burnsa | 05/21/2020 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description      | URL   |
|--------------|------------------|---|
| 699101758    | Inspection Photo | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5156897">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5156897</a> |