

## Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S97W /30SWSW

Location ID: 312470



Photo #1232 from entrance to location



Photo #0825 from inspection #699800782 conducted on 3/25/20.

## Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S97W /30SWSW

Location ID: 312470



Photo #1233 Access road has not been maintained.



Photo #0818 from inspection #699800782 conducted on 3/25/20.

## Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S97W /30SWSW

Location ID: 312470



**Photo #1234 Debris around equipment.**



**Photo #0823 from inspection #699800782 conducted on 3/25/20.**

## Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S97W /30SWSW

Location ID: 312470



Photo #1236 Debris inside pit.



Photo #0820 from inspection #699800782 conducted on 3/25/20.

## Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S97W /30SWSW

Location ID: 312470



Photo #1237 Flow line risers not LO/TO.