

## Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S98W /25NWSE

Location ID:312513



Photo #1239 from entrance to location



Photo #0826 from inspection #699800784 inspection conducted on 3/25/20.



## Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S98W /25NWSE

Location ID:312513



**Photo #1238 Access road has not been maintained.**



**Photo #0832 from inspection #699800784 inspection conducted on 3/25/20.**



## Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S98W /25NWSE

Location ID:312513



**Photo #1240 Debris around equipment.**



**Photo #0829 from inspection #699800784 inspection conducted on 3/25/20.**



## Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S98W /25NWSE

Location ID:312513



**Photo #1241 Debris inside pit.**

## Inspection Photos

**Location Name: MARALEX RESOURCES INC FEDERAL-68S98W /25NWSE**

**Location ID:312513**

**Photo # from entrance to location**