

Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S98W /35SEnw

Location ID: 312511



Photo #1242 from NW corner of location



Photo #0962 from inspection #699800907 conducted on 4/14/20.

Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S98W /35SENW

Location ID: 312511



Photo #1243 Debris inside both pits.



Photo #0963 from inspection #699800907 conducted on 4/14/20.

Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S98W /35SENW

Location ID: 312511



Photo #1244 Debris inside both pits.



Photo #0964 from inspection #699800907 conducted on 4/14/20.

Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S98W /35SENW

Location ID: 312511



Photo #1245 Multiple flowline risers not LO/TO.



Photo #0965 from inspection #699800907 conducted on 4/14/20.

Inspection Photos

Location Name: MARALEX RESOURCES INC FEDERAL-68S98W /35SENW

Location ID: 312511



Photo #1246 Multiple flowline risers not LO/TO.



Photo #1247 Unused meter run.