

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

402404717

Date Received:

05/22/2020

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10091  
Name of Operator: BERRY PETROLEUM COMPANY LLC  
Address: 5201 TRUXTUN AVENUE #100  
City: BAKERSFIELD State: CA Zip: 90339

Contact Name and Telephone:  
Name: \_\_\_\_\_  
Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_  
Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name	Phone	Email
<u>Jon Armstrong</u>	<u>661-616-3941</u>	<u>jarmstrong@bry.com</u>
<u>John Hyder</u>	<u>435-823-1861</u>	<u>jhyder@bry.com</u>
<u>Don Wilbourn</u>	<u>970-285-5207</u>	<u>dwilbourn@bry.com</u>

COGCC INSPECTION SUMMARY:

FIR Document Number: 689704637  
Inspection Date: 05/01/2020 FIR Submit Date: 05/04/2020 FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: BERRY PETROLEUM COMPANY LLC Company Number: 10091  
Address: 5201 TRUXTUN AVENUE #100  
City: BAKERSFIELD State: CA Zip: 90339

LOCATION - Location ID: 335820

Location Name: CHEVRON H07A 696 Number: \_\_\_\_\_ County: \_\_\_\_\_  
Qtrqr: SENE Sec: 7 Twp: 6S Range: 96W Meridian: 6  
Latitude: 39.540239 Longitude: -108.140458

FACILITY - API Number: 05-045-00 Facility ID: 335820

Facility Name: CHEVRON H07A 696 Number: \_\_\_\_\_  
Qtrqr: SENE Sec: 7 Twp: 6S Range: 96W Meridian: 6  
Latitude: 39.540239 Longitude: -108.140458

CORRECTIVE ACTIONS:

1 CA# 138588

Corrective Action: Install or repair required BMPs per Rule 1002.f. Date: 05/23/2020

Response: CA COMPLETED Date of Completion: 05/15/2020

Operator Comment: Corrective action work on the culvert and basin was completed by 5/15/2020. The culvert was cleared of debris and raised to hopefully reduce the clogging issues seen at the lower gradeline. Rock guarding was installed at the new pipe elevation to prevent erosion around the pipe. Additionally, the inlet sediment trap was cleaned of

debris. Pictures of the completed work have been attached to this document.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative:

**OPERATOR COMMENT AND SUBMITTAL**

Comment: Corrective action work on the culvert and basin was completed by 5/15/2020. The culvert was cleared of debris and raised to hopefully reduce the clogging issues seen at the lower gradeline. Rock guarding was installed at the new pipe elevation to prevent erosion around the pipe. Additionally, the inlet sediment trap was cleaned of debris. Pictures of the completed work have been attached to this document.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Jon Armstrong

Signed: \_\_\_\_\_

Title: EH&S Rep, Sr.

Date: 5/22/2020 9:55:43 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
402404736	Repaired Culvert 1
402404737	Repaired Culvert 2
402404745	Repaired Culvert 3
402404748	Repaired Culvert 4

Total Attach: 4 Files