

Inspection Photos
Location Name: Schneider 1414 PAD
Location ID: 432178



Photo 1 – Stained Soil at Engine Exhaust

Photo 2 – Unused Secondary Containment at Pumping Units

Inspection Photos
Location Name: Schneider 1414 PAD
Location ID: 432178




Photo 3 – Stained Soil at 2-14-8-60 Wellhead

Photo 4 – Stained Soil at 2-14-8-60 Wellhead

Inspection Photos
Location Name: Schneider 1414 PAD
Location ID: 432178



Photo 5 – Stained Soil at 1-14-8-60 Wellhead



Photo 6 – Stained Soil at South Middle-East Loadline