

Inspection Photos
Operator: BP America
API#: 067-06944
Date: 5/20/2020



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern fill slope from the southeastern corner facing westward. Revegetation is progressing on the slope with grasses such as western wheatgrass and smooth brome.



Photo 3. View of erosional head-cut approximately 4 feet wide and 6 feet deep, at the eastern edge of the project area (facing up-slope).



Photo 4. View of erosional headcut, and exposed roots downstream of headcut, facing downstream.



Photo 5. View of rig cable in the drainage, adjacent to the eastern edge of the project area.



Photo 6. View of reference area vegetation comprised of pinyon-juniper forest with understory of gambel oak, muhlygrass, and penstemon.