

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/27/2020

Submitted Date:

05/27/2020

Document Number:

690005873

FIELD INSPECTION FORM

Loc ID 427876 Inspector Name: Carlile, Craig On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

7 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Inspections		COGCCinspections@Anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
427869	WELL	PR	08/01/2018	OW	123-35140	CAMP 3N-31HZX	PR
427874	WELL	PR	08/01/2018	OW	123-35143	CAMP 29N-31HZ	PR
427875	WELL	PR	08/01/2018	OW	123-35144	CAMP FEDERAL 30C-31HZ	PR
427877	WELL	PR	08/01/2018	OW	123-35145	CAMP FEDERAL 30N-31HZ	PR
427879	WELL	PR	08/01/2018	OW	123-35147	CAMP 4N-31HZ	PR

General Comment:

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:

Comment:			
Corrective Action:			Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Equipment:

					corrective date	
Type: Plunger Lift	# 5					
Comment:						
Corrective Action:				Date:		

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
			CENTRALIZED BATTERY			
Comment:						
Corrective Action:				Date:		

Paint

Condition			
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities						
Facility ID:	427869	Type:	WELL	API Number: 123-35140	Status: PR	Insp. Status: PR
Producing Well						
Comment:	PR					
Corrective Action:						Date:
Facility ID:	427874	Type:	WELL	API Number: 123-35143	Status: PR	Insp. Status: PR
Producing Well						
Comment:	PR					
Corrective Action:						Date:
Facility ID:	427875	Type:	WELL	API Number: 123-35144	Status: PR	Insp. Status: PR
Producing Well						
Comment:	PR					
Corrective Action:						Date:
Facility ID:	427877	Type:	WELL	API Number: 123-35145	Status: PR	Insp. Status: PR
Producing Well						
Comment:	PR					
Corrective Action:						Date:
Facility ID:	427879	Type:	WELL	API Number: 123-35147	Status: PR	Insp. Status: PR
Producing Well						
Comment:	PR					
Corrective Action:						Date:

COGCC Comments		
Comment	User	Date
Routine wellhead inspecton.	carlilec	05/27/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690005874	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5159858