

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/27/2020

Submitted Date:

05/27/2020

Document Number:

699801170

**FIELD INSPECTION FORM**Loc ID 334499 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 10433

Name of Operator: LARAMIE ENERGY LLC

Address: 1401 SEVENTEENTH STREET #1401

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

18 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Laramie		cogccnotifications@laramie-energy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287345	WELL	SI	02/01/2020	GW	077-09167	WOODS-SPANGLER 15-11	SI
287346	WELL	PR	06/24/2008	GW	077-09166	WOODS-SPANGLER 15-12	PR
287347	WELL	PR	03/01/2017	GW	077-09165	WOODS-SPANGLER 15-13	PR
287348	WELL	PR	12/11/2007	GW	077-09164	WOODS-SPANGLER 15-14	PR
287349	WELL	PR	04/26/2007	GW	077-09163	WOODS-SPANGLER 21-1	PR
287350	WELL	PR	10/20/2010	GW	077-09162	WOODS-SPANGLER 22-4	PR
288356	WELL	PR	12/29/2007	GW	077-09214	WOODS-SPANGLER 16-16	PR

**General Comment:****COGCC Inspection Report Summary**

On Wednesday 5/27/20 at approximately 11:30 hours, I, Inspector Corey De Paolo, Conducted a follow up inspection at LARAMIE ENERGY LLC Woods Spangler /15-13 Pad, Location #334499 in Mesa County Colorado.

Refer to document #699800778 inspection conducted on 3/24/20. Not all previous corrective actions have been completed.

While there, I observed normal production operations.

During this inspection the following possible compliance issues were observed: Unused pipe stored on North end of location. See photo #0815 and #1264 with a previous corrective action date of 2/29/20. Unused equipment by wellhead. See photo #1266 with a corrective action date of 8/27/20.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L	Date:	
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	STORAGE OF SUPL		
Comment:	Unused pipe stored on North end of location. See photo #0815 and #1264		
Corrective Action:	Production facilities, shall be kept free of equipment and supplies not necessary for use on that lease. Remove unused pipe from location.		Date: 02/29/2020
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment by wellhead. See photo #1266		
Corrective Action:	production facilities, shall be kept free of equipment and supplies not necessary for use on that lease. Remove unused equipment from location.		Date: 08/27/2020
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	Barbed wire fence		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Livestock panels		
Corrective Action:			Date:

Type	LOCATION		
Comment:	Barbed wire fence around location.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 7		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
METHANOL	1	<50 BBLS	STEEL AST		,	
Comment:	500 gallon capacity					
Corrective Action:					Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Centralized containment			
Corrective Action:			Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	3	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:				Date:		

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: <a href="#">Separate containment</a>					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: <a href="#">Centralized containment</a>				
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 287345 Type: WELL API Number: 077-09167 Status: SI Insp. Status: SI

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Last produced January 2020

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 287346 Type: WELL API Number: 077-09166 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 287347 Type: WELL API Number: 077-09165 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 287348 Type: WELL API Number: 077-09164 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 287349 Type: WELL API Number: 077-09163 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 287350 Type: WELL API Number: 077-09162 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 288356 Type: WELL API Number: 077-09214 Status: PR Insp. Status: PR

**Producing Well**

Comment: Producing

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						
		Ditches				
		Gravel				
		Compaction				
Ditches						
Berms						
Compaction						
		Culverts				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699801171	Photos for Insp. #699801170	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5160459">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5160459</a>