

Inspection Photos

API: 061-06271

Operator: SAMSON OIL COMPANY

Inspection Date: 5/26/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06271 | Date: 5/26/2020

Inspection Photos



Photo 1. Facing west toward the location. There has been recent reclamation work performed and the location has been fenced.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06271 | Date: 5/26/2020

Inspection Photos



Photo 2. A perimeter fence has been installed around the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06271 | Date: 5/26/2020

Inspection Photos



Photo 3. Center of the location facing west. Straw mulch has been applied at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06271 | Date: 5/26/2020

Inspection Photos



Photo 4. The shovel was used to test soil compaction. Soils seem to have been decompacted in areas of the location however, it is uncertain if decompaction was performed to 18 inches.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06271 | Date: 5/26/2020