

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/27/2020

Submitted Date:

05/28/2020

Document Number:

690101888

FIELD INSPECTION FORM

Loc ID 331660 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments0 Number of Corrective Actions Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		NBL_DJBU_Inspections@NB LENERGY.COM	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
264475	WELL	SI	05/01/2019	GW	123-21075	FEATHER 31-15	EG

General Comment:

Engineering Integrity Inspection; Flowline Inspection
Photos Uploaded

Inspected FacilitiesFacility ID: 264475 Type: WELL API Number: 123-21075 Status: SI Insp. Status: EG**Flowline**

#1	Type:	of Lines	
<u>Flowline Description</u>			
Flowline Type:	Size:	Material:	
Variance:	Age:	Contents:	
<u>Integrity Summary</u>			
Failures:	Spills:	Repairs Made:	
Coatings:	H2S:	Cathodic Protection:	
<u>Pressure Testing</u>			
Witnessed:	Test Result:	Charted:	
<u>COGCC Rules(check all that apply)</u>			
<input type="checkbox"/> 1101. Installation and Reclamation <input type="checkbox"/> 1102. Operations, Maintenance, and Repair <input checked="" type="checkbox"/> 1103. Abandonment			
<u>Comment:</u>	Well (Feather 31-15) has been plugged and abandoned; COGCC form 42 notice of start of plugging operations Doc #402107072 was received on 07/12/2019. Noble contractors on location are in the process of removing equipment, tanks and dump/ process flowlines at facility/ battery. The off location wellhead flowline (runs north approx 375' from PA well to facility) is scheduled to be abandoned in place; on location dump and process flowlines to be removed. COGCC form 42 Flowline pre abandonment - 30-day notice Doc #402307923 was received on 2/10/2020. COGCC form 44 (off location flowline abandonment) notice Doc #402369190 was received on 04/13/2020. No corrective actions were identified during this field inspection.		
Corrective Action:			Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690101893	Signage; work in progress on location (view SW)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5160676
690101894	View from (PA) wellhead N to battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5160677