

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	Adequate		
Corrective Action:			Date:

Emergency Contact Number:

Comment:		
Corrective Action:		Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Compressor not in use, pulley belts removed from motor inside compressor house. Old hose lying on ground behind tank battery		
Corrective Action:	Comply with Rule 603.f unused equipment		Date: 08/29/2020

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:

Type	OTHER		
Comment:	Gas meter run has square tubing.		
Corrective Action:			Date:

Equipment:

Type	#		corrective date
Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: shares containment with crude tank				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					
Date:					

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 470203 Type: TANK API Number: - Status: AC Insp. Status: AC**Producing Well**Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Friday 5/29/2020 at approximately 0900 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Top Operating Company location:</p> <p style="text-align: right;">Counter 1-AD Battery at</p> <p>Facility #470203 in Weld County Colorado. While there, I observed Tank Battery. During this inspection the following possible compliance issues were observed: 603.f Unused Equipment: Compressor is in disrepair and unused: unused hose behind tank battery. CA date 8-29-2020 See attached photos 7, 8 and 10. During this inspection the following possible compliance issues was observed and corrected: 605.d Mechanical issue: Flat plug on separator was dripping water and has was replaced by lease operator while I was on location see attached video. No CA necessary. 1002.(2).D : stained soil where drip was on separator was dug up and removed/replaced by lease operator while I was on location See photo 4. No CA necessary. Location is dry, weather is clear. No follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. Continuing education COGCC Inspection Report Summary. This is a summary of inspection report.</p>	revasr	05/29/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699301825	TB pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5162369
699301826	Drip vid	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5162370