

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

05/29/2020

Submitted Date:

05/31/2020

Document Number:

696103028

FIELD INSPECTION FORM
 Loc ID 430706 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

18 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
430705	WELL	TA	12/01/2019	OW	123-36262	Jeanie AB10-01R	TA

General Comment:

This is a WELL inspection.

Well(s): 1: Temporarily Abandoned | TA.

Battery: Inactive | Shut-down.

Centralized Battery serves 2 Location IDs (416754, 430706).

(Well(s): 1: Shut-In | SI ; 1: Temporarily Abandoned | TA).

Refer to Field Inspection Report doc. #696103026 and/or Location ID #416754 for Battery / Facility, Equipment info.

Follow-up to Field Inspection Report doc. #696300530 dated 08/22/2019.

3 of 3 prior Corrective Action(s) appear addressed.

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type			
Comment:	Refer to Field Inspection Report doc. #696103026 and/or Location ID #416754 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	<p>Prior insp: Unused tubing at wellsite. Remove unused tubing at wellsite. Comply w/ Rule 603.f. Corrective Action date: 09/25/2019.</p> <p>This insp: * Unused tubing at wellsite NOW removed. See photos #11, 12.</p>		
Corrective Action:		Date:	
Type	UNUSED EQUIPMENT		
Comment:	<p>Prior insp: Unused wellhead parts and pollution pot at wellsite. Remove unused wellhead parts and pollution pot at wellsite. Comply w/ Rule 603.f. Corrective Action date: 09/25/2019.</p> <p>This insp: * Unused wellhead parts and pollution pot at wellsite NOW removed. See photos #5-10.</p>		
Corrective Action:		Date:	
Type	OTHER		
Comment:	<p>Prior insp: Stained Soil at wellsite. Remove and/or remediate stained soil at wellsite. Comply with Rule 907.e. Corrective Action date: 09/25/2019.</p> <p>This insp: * Stained soil at wellsite now appears mitigated. See photos #3, 4.</p>		
Corrective Action:		Date:	

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:		Date:	
Type			
Comment:	Refer to Field Inspection Report doc. #696103026 and/or Location ID #416754 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Iron pipe.		
Corrective Action:		Date:	

Equipment:

Type: Other	#		corrective date
Comment:	Wellhead: w/ master & casing valves.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Electric motor		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	At wellsite: 1: Electric transformer.		
Corrective Action:		Date:	
Type:	#		
Comment:	Refer to Field Inspection Report doc. #696103026 and/or Location ID #416754 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
			CENTRALIZED BATTERY		,	

Comment:	Centralized Battery serves 2 Location IDs (416754, 430706). Refer to Field Inspection Report doc. #696103026 and/or Location ID #416754 for Battery / Facility, Equipment info.	
Corrective Action:		Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected FacilitiesFacility ID: 430705 Type: WELL API Number: 123-36262 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily AbandonedReminder: EQUIPMENT PRESENT/DISCONNECTEDComment:

Temporarily Abandoned | TA.
Wellhead disconnected from flowline.
Form 4 Sundry doc. #402143284 indicates TA status date: 07/17/2019. Approved.
Form 42 doc. #402113700 indicates 10-day MIT notice date: 07/26/2019. Approved.
Form 21-MIT doc. #402139553 indicates MIT date: 07/25/2019. Approved.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On FRI 05/29/2020 at approximately 14:26 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: Jeanie /AB10-01R Pad Location ID: 430706 Well Name: Jeanie AB10-01R API: 05-123-36262 Location County: Weld County, Colorado Weather: Partly cloudy, dry.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Inactive Shut-down.</p> <p>Centralized Battery serves 2 Location IDs (416754, 430706). (Well(s): 1: Shut-In SI ; 1: Temporarily Abandoned TA).</p> <p>Refer to Field Inspection Report doc. #696103026 and/or Location ID #416754 for Battery / Facility, Equipment info.</p> <p>Follow-up to Field Inspection Report doc. #696300530 dated 08/22/2019. During this inspection, the following prior possible compliance issues appear to be addressed: 1.) Stained Soil at wellsite. Remove and/or remediate stained soil at wellsite. Comply with Rule 907.e. Corrective Action date: 09/25/2019. * Stained soil at wellsite now appears mitigated. See photos #3, 4.</p> <p>2.) Unused wellhead parts and pollution pot at wellsite. Remove unused wellhead parts and pollution pot at wellsite. Comply w/ Rule 603.f. Corrective Action date: 09/25/2019. * Unused wellhead parts and pollution pot at wellsite NOW removed. See photos #5-10.</p> <p>3.) Unused tubing at wellsite. Remove unused tubing at wellsite. Comply w/ Rule 603.f. Corrective Action date: 09/25/2019. * Unused tubing at wellsite NOW removed. See photos #11, 12.</p> <p>During this inspection, NO New/Current possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	05/31/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696103029	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5162681