

Inspection Photos

API: 071-06609

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 5/29/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06609 | Date: 5/29/2020

Inspection Photos



Photo 1. The erosion gully observed in previous inspection has been repaired and rock rip/rap has been installed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06609 | Date: 5/29/2020

Inspection Photos



Photo 2. Facing southwest along the main road ascending the hill. Rock check dams have been installed along the road to the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06609 | Date: 5/29/2020

Inspection Photos



Photo 3. Facing northeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06609 | Date: 5/29/2020

Inspection Photos



Photo 4. Facing north toward the fill slope. Vegetation is well established in the interim reclamation areas.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06609 | Date: 5/29/2020