

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

05/28/2020

Submitted Date:

06/01/2020

Document Number:

700401718**FIELD INSPECTION FORM**
 Loc ID 316684 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 10341Name of Operator: PUCKETT LAND COMPANYAddress: 5460 S. QUEBEC STREET - STE #250City: GREENWOOD State: CO Zip: 80111**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
Stearns, Eric	303-463-1000	ericstearns@puckettland.com	President

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
298469	WELL	XX	09/22/2008	GW	103-11386	FIGURE FOUR RANCH 499-14-22	PA

General Comment:

Follow up to inspection 679704323 dated 6-3-2019 for well Figure Four Ranch 499-14-22. That inspection failed to include a corrective action of:

- 1) Submit Form 6 with the Subsequent Report of Abandonment filled out. Complete by 7-1-2020.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☒**Spills:**

Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 298469 Type: WELL API Number: 103-11386 Status: XX Insp. Status: PA**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Form 6 document 400289941 was submitted on 5-29-2012 by Puckett Land Company for the intent to abandon.

Form 4 document 400818786 was submitted on 4-1-2015 by Encana indicating reclamation was completed.

No surface evidence of well head during the 6-3-2019 inspection.

Corrective Action: Submit Form 6 with the Subsequent Report of Abandonment filled out.

Date: 07/01/2020

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700401719	Location photos from 6-3-2019.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5163372