

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/01/2020

Submitted Date:

06/01/2020

Document Number:

699301851

FIELD INSPECTION FORM

Loc ID 429055 Inspector Name: Revas, Robbie On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|-------------------------------|---------------------------------|
| , | | COGCCinspections@anadarko.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 429053 | WELL | PR | 06/01/2019 | OW | 123-35657 | THOMASON 2N-9HZ | PR |
| 429054 | WELL | PR | 06/01/2019 | OW | 123-35658 | THOMASON 2C-9HZ | PR |
| 429056 | WELL | PR | 06/01/2019 | OW | 123-35659 | THOMASON 27N-W9HZ | PR |

General Comment:

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|--------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | adequate x 3 | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|----------------------|-------|--|
| Comment: | <input type="text"/> | Date: | |
| Corrective Action: | <input type="text"/> | | |

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

| | | | |
|--------------------|----------|-------|--|
| Type | WELLHEAD | | |
| Comment: | AG fence | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|---------------------------|--|-------|-----------------|
| Type: Bradenhead | # 3 | | corrective date |
| Comment: | all appear to be plumbed to surface | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 4 | | |
| Comment: | Automation, transformer and electric panel | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 3 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

| Inspected Facilities | | | |
|----------------------------|-------------------|------------------------------|---|
| Facility ID: <u>429053</u> | Type: <u>WELL</u> | API Number: <u>123-35657</u> | Status: <u>PR</u> Insp. Status: <u>PR</u> |
| Producing Well | | | |
| Comment: <u>PR</u> | | | |
| Corrective Action: | | Date: | |
| Facility ID: <u>429054</u> | Type: <u>WELL</u> | API Number: <u>123-35658</u> | Status: <u>PR</u> Insp. Status: <u>PR</u> |
| Producing Well | | | |
| Comment: <u>PR</u> | | | |
| Corrective Action: | | Date: | |
| Facility ID: <u>429056</u> | Type: <u>WELL</u> | API Number: <u>123-35659</u> | Status: <u>PR</u> Insp. Status: <u>PR</u> |
| Producing Well | | | |
| Comment: <u>PR</u> | | | |
| Corrective Action: | | Date: | |

| COGCC Comments | | |
|---|--------|------------|
| Comment | User | Date |
| <p>COGCC Inspection Report Summary On Monday 06/01/2020 at approximately 1505 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Kerr McGee location:</p> <p style="text-align: center;">Thomason 15C-4HZ at Location</p> <p>#429055 in Weld County Colorado. While there, I observed a producing multi-well wellsite. During this inspection no issue was observed: See attached photos. Location is dry, weather is clear. No follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. Continuing education COGCC Inspection Report Summary. This is a summary of inspection report.</p> | revasr | 06/01/2020 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------|---|
| 699301852 | location pics | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5164020 |