

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/26/2020

Submitted Date:

05/26/2020

Document Number:

700700779**FIELD INSPECTION FORM**

Loc ID 414152	Inspector Name: Ramsey, Scott	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 11 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
Operator Information: OGCC Operator Number: <u>10456</u> Name of Operator: <u>CAERUS PICEANCE LLC</u> Address: <u>1001 17TH STREET #1600</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:			
Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
413361	WELL	PR	07/31/2011	GW	045-18788	Rulison Federal 20-11C (17M)	PR
413367	WELL	PR	09/23/2011	GW	045-18782	Double B Ranch 18-44A (17M)	PR
413368	WELL	PR	01/18/2012	GW	045-18781	Rulison Federal 20-11A (17M)	PR
413369	WELL	PR	08/03/2011	GW	045-18780	Rulison Federal 20-11B (17M)	PR
413372	WELL	PR	09/01/2011	GW	045-18777	Double B Ranch 18-44B (17M)	SI
413373	WELL	PR	08/29/2011	GW	045-18776	Double B Ranch 18-44C (17M)	PR
413374	WELL	PR	09/01/2011	GW	045-18775	Double B Ranch 18-44D (17M)	PR
413377	WELL	PR	07/15/2011	GW	045-18772	Rulison Federal 19-41C (17M)	PR

General Comment:

COGCC Inspection Report Summary
 On Tuesday 5/26/20 at approximately 1:30 PM, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus 17M, at Location # 414152 in Garfield Colorado.
 While there, I observed normal production operations.
 During this inspection the following possible compliance issues were observed:
 • Random debris at tank battery, separators and well heads
 Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.
 This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:	Random debris at tank battery, separators and well heads		
Corrective Action:	Remove all debris	Date:	06/09/2020

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 11		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 8		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 7		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	6	400 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
			Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 413361	Type: WELL	API Number: 045-18788	Status: PR	Insp. Status: PR
Producing Well				
Comment: producing				
Corrective Action:		Date:		
Facility ID: 413367	Type: WELL	API Number: 045-18782	Status: PR	Insp. Status: PR
Producing Well				
Comment: producing				
Corrective Action:		Date:		
Facility ID: 413368	Type: WELL	API Number: 045-18781	Status: PR	Insp. Status: PR
Producing Well				
Comment: producing				
Corrective Action:		Date:		
Facility ID: 413369	Type: WELL	API Number: 045-18780	Status: PR	Insp. Status: PR
Producing Well				
Comment: producing				
Corrective Action:		Date:		
Facility ID: 413372	Type: WELL	API Number: 045-18777	Status: PR	Insp. Status: SI
Idle Well				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____				
Comment: shut in at time of inspection				
Corrective Action:		Date:		
Facility ID: 413373	Type: WELL	API Number: 045-18776	Status: PR	Insp. Status: PR
Producing Well				
Comment: producing				
Corrective Action:		Date:		
Facility ID: 413374	Type: WELL	API Number: 045-18775	Status: PR	Insp. Status: PR
Producing Well				
Comment: producing				
Corrective Action:		Date:		
Facility ID: 413377	Type: WELL	API Number: 045-18772	Status: PR	Insp. Status: PR

Producing Well			
Comment:	producing		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Sediment Traps						
Waddles						
Ditches		Ditches				
Hydro Mulch		Gravel				
Berms		Culverts				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402406050	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5159019
700700784	Photos for 17M	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5159015