

Inspection Photos

Location Name: CVR /5-63-32_33 NWSW

Location #: 449306



Colorado Oil & Gas Conservation Commission
40.35246, -104.4687, 4518.9ft, 23°
06/01/2020 15:15:36

Photo #1

CVR 5-63-32-4841B2 (05-123-44255)
CVR 5-63-32-4841C2 (05-123-44257)
CVR 5-63-32-4956B2 (05-123-44256)
CVR 5-63-32-6457D2 (05-123-44253)
CVR 5-63-32-6457B2B (05-123-44254)

Wellsites **Producing | PR**



Colorado Oil & Gas Conservation Commission
40.35617, -104.46674, 4528.3ft, 188°
06/01/2020 16:05:14

Photo #2

CVR 5-63-32-1609CH, CVR 5-63-32-1609CDH,
CVR 5-63-32-1724BH, CVR 5-63-32-3225CH,
CVR 5-63-32-3225CDH, CVR 5-63-32-3340BH,
CVR 5-63-32-4841B2, CVR 5-63-32-4841C2,
CVR 5-63-32-4956B2, CVR 5-63-32-6457D2,
CVR 5-63-32-6457B2B (11: wells)

Battery site

Active

Inspection Photos

Location Name: CVR /5-63-32_33 NWSW

Location #: 449306



Photo #3

CVR 5-63-32-6457B2B

Wellsite separator (South pad)

Incident: Post release.

No Equipment Damage.

Stained soil contained on tarp.

Remediation progressing.