

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/01/2020

Submitted Date:

06/01/2020

Document Number:

696103032

FIELD INSPECTION FORMLoc ID 449306 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10071

Name of Operator: HIGHPOINT OPERATING CORPORATION

Address: 555 17TH ST STE 3700

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

20 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Chesson, Robert		robert.chesson@state.co.us	
Neighbors, Cory		cneighbors@hpres.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
449308	WELL	PR	08/01/2017		123-44253	CVR 5-63-32-6457D2	PR
449309	WELL	PR	08/30/2017	OW	123-44254	CVR 5-63-32-6457B2B	PR
449310	WELL	PR	08/30/2017	OW	123-44255	CVR 5-63-32-4841B2	PR
449311	WELL	PR	08/01/2017	OW	123-44256	CVR 5-63-32-4956B2	PR
449312	WELL	PR	08/17/2017	OW	123-44257	CVR 5-63-32-4841C2	PR

General Comment:

This is a WELL inspection.
Well(s): 5: Producing | PR.
Battery: Active.

Centralized Battery serves 2 Location IDs (432011, 449306).
(Well(s): 11: Producing | PR ; 1: Abandoned Location | AL).

Refer to Field Inspection Report doc. #696103030 and/or Location ID #432011
for Battery / Facility, Equipment info.

Also inspected post release incident at CVR 5-63-32-6457B2B (05-123-44254) wellsite separator.
Stained soil contained in tarp. No equipment damage. Remediation in progress. Company wellsite operator arrived during inspection.
Advised that tarped stained soil would be removed tomorrow.

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action	L		Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type			
Comment:	Refer to Field Inspection Report doc. #696103030 and/or Location ID #432011 for Battery / Facility, Equipment info.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	OTHER		
Comment:	Post release incident at CVR 5-63-32-6457B2B (05-123-44254) wellsite separator. Stained soil contained in tarp. No equipment damage. Remediation in progress. Company wellsite operator arrived during inspection. Advised that tarped stained soil would be removed tomorrow. See photo #3.		
Corrective Action:			Date:
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment: _____			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type			
Comment:	Refer to Field Inspection Report doc. #696103030 and/or Location ID #432011 for Battery / Facility, Equipment info.		
Corrective Action:			Date:
Equipment:			
Type: Bird Protectors		# 6	corrective date
Comment:		At wellsites.	
Corrective Action:		Date:	
Type: Ancillary equipment		# 4	
Comment:		At wellsites: Protective concrete barriers.	

Corrective Action:		Date:	
Type: Bradenhead	# 5		
Comment:	5: wellsites. Appears plumbed to surface.		
Corrective Action:		Date:	
Type: Plunger Lift	# 5		
Comment:	5: wellsites.		
Corrective Action:		Date:	
Type:	#		
Comment:	Refer to Field Inspection Report doc. #696103030 and/or Location ID #432011 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 6		
Comment:	At wellsites.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 10		
Comment:	At wellsites: 10: Apportioned		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.355567,-104.466636
Comment:	Centralized Battery serves 2 Location IDs (432011, 449306). Refer to Field Inspection Report doc. #696103030 and/or Location ID #432011 for Battery / Facility, Equipment info.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
------	--

Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	449308	Type:	WELL	API Number:	123-44253	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing PR.								
Corrective Action:						Date:			
Facility ID:	449309	Type:	WELL	API Number:	123-44254	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing PR.								
Corrective Action:						Date:			
Facility ID:	449310	Type:	WELL	API Number:	123-44255	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing PR.								
Corrective Action:						Date:			
Facility ID:	449311	Type:	WELL	API Number:	123-44256	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing PR.								
Corrective Action:						Date:			
Facility ID:	449312	Type:	WELL	API Number:	123-44257	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing PR.								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On MON 06/01/2020 at approximately 15:15 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: HIGHPOINT OPERATING CORPORATION Location Name: CVR /5-63-32_33 NWSW Location ID: 449306 Well Names: CVR 5-63-32-4841B2, CVR 5-63-32-4841C2, CVR 5-63-32-1724BH, CVR 5-63-32-6457D2, CVR 5-63-32-6457B2B. API: 05-123-44255, 05-123-44257, 05-123-44256, 05-123-44253, 05-123-44254. Location County: Weld County, Colorado Weather: Partly cloudy, dry.</p> <p>While there, I observed: Well(s): 5: Producing PR. Battery: Active.</p> <p>Centralized Battery serves 2 Location IDs (432011, 449306). (Well(s): 11: Producing PR ; 1: Abandoned Location AL).</p> <p>Refer to Field Inspection Report doc. #696103030 and/or Location ID #432011 for Battery / Facility, Equipment info.</p> <p>Also inspected post release incident at CVR 5-63-32-6457B2B (05-123-44254) wellsite separator. Stained soil contained in tarp. No equipment damage. Remediation in progress. Company wellsite operator arrived during inspection. Advised that tarped stained soil would be removed tomorrow. See photo #3.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	06/02/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696103033	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5164139