

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/20/2020

Submitted Date:

06/02/2020

Document Number:

687400797**FIELD INSPECTION FORM**Loc ID 320320 Inspector Name: Huck, Keith On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 76859Name of Operator: SCHREIDER & COMPANY INCAddress: 9227 E LINCOLN AVE SUITE 200City: LONE TREE State: CO Zip: 80124**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**13 Number of Comments4 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
C, RUDY	303-659-8203	darnold@agcsi.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203444	WELL	SI	07/01/2018	GW	001-09003	HOWELL 1-11	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	What appears to be a propane tank is sitting unused next to the pumpjack. See attached pictures		
Corrective Action:	Comply with Rule 603.f .	Date:	08/03/2020
Type	DEBRIS		
Comment:	Debris and Trash all around tank battery and spearator. See attached pictures		
Corrective Action:	Comply with Rule 603.f .	Date:	06/12/2020

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	PUMP JACK		
Comment:	4 strand barbed wire in disrepair. See attached pictures		
Corrective Action:	Location is within a designated setback location, install fencing per Rule 604.c.(2)M.	Date:	06/12/2020
Type	TANK BATTERY		
Comment:	4 strand barbed wire in disrepair. See attached pictures		
Corrective Action:	Location is within a designated setback location, install fencing per Rule 604.c.(2)M.	Date:	06/12/2020
Type	LOCATION		
Comment:	4 strand barbed wire		
Corrective Action:		Date:	

Type	SEPARATOR		
Comment:	4 strand barbed wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLS	STEEL AST		39.881465,-104.288898	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity		Permeability (Wall)		Permeability (Base)		Maintenance			
Earth	Adequate		Walls Sufficent		Base Sufficent		Adequate			
Comment:										
Corrective Action:									Date:	
Contents		#	Capacity	Type		Tank ID	SE GPS			
PRODUCED WATER		1	300 BBLS	STEEL AST			,			
Comment:										

Corrective Action:		Date:	
Paint			
Condition	Adequate		
Other (Content)			
Other (Capacity)			
Other (Type)			
Berms			
Type	Capacity	Permeability (Wall)	Permeability (Base)
Earth	Adequate	Walls Sufficient	Base Sufficient
Comment:			
Corrective Action:			Date:
Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 203444 Type: WELL API Number: 001-09003 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: EQUIPMENT ONSITEComment: SICorrective Action: Date: **COGCC Comments**

Comment

User

Date

COGCC Inspection Report Summary

On (Wednesday) (05/06/2020) at approximately (10:00am), I, Inspector (Keith Huck), conducted an on-site inspection at (Howell 1-11) (Schreider and Company), at (Location#320320) in (Adams,County) Colorado.

While there, I observed Production.

During this inspection the following possible compliance issues were observed:

Debris and Trash all around tank battery and spearator. Comply with Rule 603.f .

Corrective Action Date: 06/12/2020 See attached pictures

What appears to be a propane tank is sitting unused next to the pumpjack. Comply with Rule 603.f . Corrective Action Date: 08/03/2020 See attached pictures

4 strand barbed wire in disrepair. Location is within a designated setback location, install fencing per Rule 604.c.(2)M. Corrective Action Date: 06/12/2020 See attached pictures

A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

huckk

06/02/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687400798	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5164647