

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:			Date:
Type	BATTERY		
Comment:	Adequate		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:			Date:

Emergency Contact Number:

Comment:	Adequate		
Corrective Action:			Date: _____

Good Housekeeping:

Type	DEBRIS		
Comment:	Debris all around tanks and production equipment. See attached pictures		
Corrective Action:	Location is within a designated setback location, remove trash or debris per Rule 604.c. (2)P.		Date: <u>06/17/2020</u>

Overall Good:

Spills:

Type	Area	Volume	

In Containment: No

Comment: _____

Multiple Spills and Releases?

Equipment:

Type			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface		
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Other	# 2		
Comment:	Propane Tanks		
Corrective Action:			Date:

Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	PBV FIBERGLASS		
Comment:	Amount label is missing on produced water tank				
Corrective Action:	Install sign to comply with Rule 210.d.			Date:	08/03/2020

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Shares berm with production tank. See attached pictures				
Corrective Action:	Install sign to comply with Rule 210.d.			Date:	07/03/2020

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		39.918720,-104.319619
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 202754 Type: WELL API Number: 001-08159 Status: SI Insp. Status: SI**Idle Well**Purpose: Shut In Temporarily Abandoned Reminder: EQUIPMENT ONSITEComment: SICorrective Action: Date: **COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary On (Wednesday) (05/06/2020) at approximately (10:40am), I, Inspector (Keith Huck), conducted an on-site inspection at (Nichols Well#1) (Natural Resources Group Inc), at (Location#320127) in (Adams,County) Colorado. While there, I observed Production. During this inspection the following possible compliance issues were observed: Debris all around tanks and production equipment. See attached pictures Location is within a designated setback location, remove trash or debris per Rule 604.c. (2)P. Corrective Action Date:06/17/2020 Amount label is missing on produced water tank. See attached pictures Install sign to comply with Rule 210.d. Corrective Action Date: 08/03/2020 A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	huckk	06/02/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687400800	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5164726