

Inspection Photos
Operator: Catamount Energy
API#: 067-05362
Date: 6/1/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing with rubber rabbitbrush, smooth brome, and Indian ricegrass.



Photo 3. View of project facilities down-slope and northwest of the wellpad shown in Photo 1. Pit with unknown status adjacent to facilities (see inset).



Photo 4. View of reference area comprised of pinyon and juniper woodland with gambel oak, sagebrush, and mixed grasses and forbs such as penstemon and Indian ricegrass.