

Inspection Photos
Operator: Catamount Energy
API#: 067-05373
Date: 6/1/2020



Photo 1. View of the project area from the southern edge facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing with rubber rabbitbrush, smooth brome, and Indian ricegrass.



Photo 3. View of Canada thistles within the eastern project area.



Photo 4. View of the reference area comprised of sagebrush shrubland with an understory of grasses such as squirreltail and forbs such as penstemon.