

**Inspection Photos**  
**Operator: Catamount Energy**  
**API#: 067-09073**  
**Date: 6/1/2020**



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Revegetation is progressing with smooth brome, crested wheatgrass, and western wheatgrass.



Photo 3. View of the eastern project area from the northeastern corner facing westward.



Photo 4. View of reference area comprised of open grass field with grasses such as smooth brome and western wheatgrass.