

Inspection Photos  
Operator: Logos Operating  
API#: 067-05371  
Date: 6/3/2020



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the western fill slope from the southwestern corner facing northward. Revegetation is progressing with sagebrush, Indian ricegrass, and rubber rabbitbrush.





Photo 3. View of area in the southwestern project area where erosion was identified in 2016, it appears that cobbles were placed, and is evident that erosion continues here.





Photo 4. View of erosional channel at the well pad entrance, approximately 18 inches wide and deep (hard had in place for scale). Area of erosion was identified during 2016 reclamation inspection.





Photo 5. View of numerous metal rings that appear to have been exposed from erosion on the well pad cut-slope. Debris needs to be removed. Cut-slope needs stabilization.





Photo 6. View of reference area comprised of pinyon and juniper woodland with understory of black sage, squirreltail, and Navajo tea.