

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type WELLHEAD

Comment: Red AG fencing

Corrective Action:

Date: _____

Equipment:

corrective date

Type: Pump Jack # 1

Comment:

Corrective Action:

Date: _____

Type: Ancillary equipment # 1

Comment: Electric / automation

Corrective Action:

Date: _____

Type: Prime Mover # 1

Comment: Electric motor

Corrective Action:

Date: _____

Type: Bradenhead # 2

Comment:

Corrective Action:

Date: _____

Type: Plunger Lift # 1

Comment:

Corrective Action:

Date: _____

Venting:

Yes/No NO

Comment:

Corrective Action:

Date: _____

Flaring:

Type

Comment:

Corrective Action:

Date: _____

Inspected Facilities

Facility ID: 435006 Type: WELL API Number: 123-38419 Status: PR Insp. Status: PR

Facility ID: 435009 Type: WELL API Number: 123-38420 Status: SI Insp. Status: SI

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules. At time of inspection weather conditions were sunny and calm.	medinaj	06/04/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699501360	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5166581