

Inspection Photos

API: 05-071-09402

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 6/2/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09402 | Date: 6/2/2020

Inspection Photos



Photo 1. Facing south at the beginning of the access road which was approved by variance to remain.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09402 | Date: 6/2/2020

Inspection Photos



Photo 2. Facing south along the drainage crossing. There are two large culverts installed in the drainage crossing. There was no stormwater issues observed in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09402 | Date: 6/2/2020

Inspection Photos



Photo 3. Facing east along the reclaimed portion of the access road. Perineal vegetation is uniformly established.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09402 | Date: 6/2/2020

Inspection Photos



Photo 4. Facing southeast toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09402 | Date: 6/2/2020

Inspection Photos



Photo 5. Facing southeast toward the location. There is a berm installed along the contour of the slope with rock rip/rap outlet protection. Berm can be seen In left side of photo.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09402 | Date: 6/2/2020

Inspection Photos



Photo 6. Facing northwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09402 | Date: 6/2/2020

Inspection Photos



Photo 7. Facing west toward the upper portion of the reclaimed location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09402 | Date: 6/2/2020

Inspection Photos



Photo 8. Facing southeast at the top portion of the location. There is a perimeter run-on ditch at the top portion of the location. This area should have been fully contoured into the terrain in order to fully reclaim this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09402 | Date: 6/2/2020

Inspection Photos



Photo 9. Facing northeast at the location. The upper run-on ditch and berms are directed toward the riprap drainage area. No stormwater issues were observed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-09402 | Date: 6/2/2020