

Inspection Photos
Operator: Catamount Energy
API#: 067-08631
Date: 6/3/2020



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the eastern fill slope from the southeastern corner facing northward. Revegetation is progressing with crested wheatgrass, western wheatgrass, and intermediate wheatgrass.



Photos 3/4. View of Russian knapweeds within the eastern project area. Approximately 2000 observed.



Photo 5. View of the western project area from the southwestern corner facing northward.



Photo 6. View of reference area comprised of pinyon and juniper woodland with understory of black sage, squirreltail, blue grama, and Navajo tea.