

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/04/2020

Submitted Date:

06/04/2020

Document Number:

699301891

FIELD INSPECTION FORM

Loc ID 442961 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

17 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		COGCCinspections@anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
442954	WELL	PR	07/04/2016	OW	123-42068	SUNFLOWER 40C-17HZ	PR
442955	WELL	PR	09/01/2018	OW	123-42069	SUNFLOWER 7N-17HZ	PR
442956	WELL	PR	09/01/2018	OW	123-42070	SUNFLOWER 8N-17HZ	PR
442957	WELL	PR	09/01/2018	OW	123-42071	SUNFLOWER 7C-17HZ	PR
442958	WELL	PR	09/01/2018	OW	123-42072	SUNFLOWER 25G-17HZ	PR
442959	WELL	PR	09/01/2018	OW	123-42073	SUNFLOWER 24N-17HZ	PR
442960	WELL	PR	09/01/2018	OW	123-42074	SUNFLOWER 40N-17HZ	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	adequate x 7		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	barbless wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Ag fence x 7		
Corrective Action:		Date:	

Equipment:			corrective date
Type: FWKO	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 7		
Comment:	all appear to be plumbed to surface		
Corrective Action:		Date:	
Type: Ancillary equipment	# 20		
Comment:	automation and electric panels		
Corrective Action:		Date:	
Type: Plunger Lift	# 7		

Comment:			
Corrective Action:		Date:	
Type: LACT	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 7		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 9		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
			Date:	

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	OTHER	PBV FIBERGLASS		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	210 bbl	

Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: shares containment with crude tank					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities									
Facility ID:	442954	Type:	WELL	API Number:	123-42068	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	442955	Type:	WELL	API Number:	123-42069	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	442956	Type:	WELL	API Number:	123-42070	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	442957	Type:	WELL	API Number:	123-42071	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	442958	Type:	WELL	API Number:	123-42072	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	442959	Type:	WELL	API Number:	123-42073	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	442960	Type:	WELL	API Number:	123-42074	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
COGCC Comments									

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday 6/4/2020 at approximately 1510 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Kerr McGee location:</p> <p style="text-align: center;">Sunflower 24N-17HZ at Location #</p> <p>442961 in Weld County Colorado.</p> <p>While there, I observed a multi-well pad and tank battery.</p> <p>During this inspection no compliance issues were observed:</p> <p>See attached photos.</p> <p>Location is dry, weather is cloudy.</p> <p>No follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>Continuing education COGCC Inspection Report Summary.</p> <p>This is a summary of inspection report.</p>	revasr	06/04/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699301892	TB pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5166979
699301893	Location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5166980