

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/04/2020

Submitted Date:

06/05/2020

Document Number:

696103067**FIELD INSPECTION FORM**Loc ID 330357 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:13 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
251159	WELL	TA	02/01/2017	OW	123-18962	SLW GREEN STATE BB 18-11	TA

General Comment:

This is a WELL inspection.
Well(s): 1: Temporarily Abandoned | TA.
Battery: Active.

Centralized Battery serves 5 Location IDs (428198, 330538, 330539, 330357, 330358).
(Well(s): 1: Producing | PR ; 2: Shut-In | SI ; 2: Temporarily Abandoned | TA).

Refer to Field Inspection Report doc. #696103044 and/or Location ID #428198
for Battery / Facility, Equipment info.

Follow-up to Field Inspection Report doc. #696103050 dated 06/02/2020.

Location				
Lease Road:				
Type	Access			
comment:	Adequate			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Refer to Field Inspection Report doc. #696103044 and/or Location ID #428198 for Battery / Facility, Equipment info.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Good Housekeeping:				
Type	UNUSED EQUIPMENT			
Comment:	<p>Prior insp: Unused well parts at wellsite. Remove unused parts at wellsite. Comply w/ Rule 603.f. Prior issue was stated as a "Good Housekeeping" comment in lieu of a Corrective Action.</p> <p>This insp: * Unused well parts at wellsite NOW removed. See photos #1, 2.</p>			
Corrective Action:				Date:
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	WELLHEAD			
Comment:	Iron panel.			
Corrective Action:				Date:
Type				
Comment:	Refer to Field Inspection Report doc. #696103044 and/or Location ID #428198 for Battery / Facility, Equipment info.			
Corrective Action:				Date:
Equipment:				
Type: Bradenhead	# 1			corrective date
Comment:	Appears plumbed to surface.			
Corrective Action:				Date:

Type: Other	# 1	
Comment:	Wellhead w/ master & casing valves.	
Corrective Action:		Date:
Type:	#	
Comment:	Refer to Field Inspection Report doc. #696103044 and/or Location ID #428198 for Battery / Facility, Equipment info.	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.396340,-104.478730
Comment:	Centralized Battery serves 5 Location IDs (428198, 330538, 330539, 330357, 330358). (Well(s): 1: Producing PR ; 2: Shut-In SI ; 2: Temporarily Abandoned TA). Refer to Field Inspection Report doc. #696103044 and/or Location ID #428198 for Battery / Facility, Equipment info.				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	251159	Type:	WELL	API Number:	123-18962	Status:	TA	Insp. Status:	TA
Idle Well									
Purpose:		<input type="checkbox"/> Shut In		<input checked="" type="checkbox"/> Temporarily Abandoned		Reminder: EQUIPMENT PRESENT/DISCONNECTED			
Comment:		<div>Temporarily Abandoned TA. Well disconnected from flowline. Yellow LTSI tag posted at well. Locked-Out, Tagged-Out LOTO. COGCC records indicate last production: 04/2015. SI/TA well per Alternative Mechanical Integrity Assurance Program (Alternative Program). Doc #02385001 (NOBLE). Form 4 Sundry doc. #402079635 indicates Temporarily Abandoned TA status: 04/13/2015. Approved.</div>							
Corrective Action:							Date:		

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On TUE 06/04/2020 at approximately 13:54 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: SLW GREEN STATE BB65N63W /18NESW Location ID: 330357 Well Name: SLW Green State BB 18-11 API: 05-123-18962 Location County: Weld County, Colorado Weather: Mostly cloudy, dry.</p> <p>While there, I observed: Well(s): 1: Temporarily Abandoned TA. Battery: Active.</p> <p>Centralized Battery serves 5 Location IDs (428198, 330538, 330539, 330357, 330358). (Well(s): 1: Producing PR ; 2: Shut-In SI ; 2: Temporarily Abandoned TA).</p> <p>Refer to Field Inspection Report doc. #696103044 and/or Location ID #428198 for Battery / Facility, Equipment info.</p> <p>Follow-up to Field Inspection Report doc. #696103050 dated 06/02/2020. During this inspection, the following prior possible compliance issues appear to be addressed: 1.) Unused well parts at wellsite. Remove unused parts at wellsite. Comply w/ Rule 603.f. Prior issue was stated as a "Good Housekeeping" comment in lieu of a Corrective Action. * Unused well parts at wellsite NOW removed. See photos #1, 2.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	06/05/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696103068	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5167334