

Inspection Photos
Operator: Catamount Energy
API#: 067-08206
Date: 6/3/2020



Photo 1. View of the project area from the northeastern corner facing center.




Photo 2. View of the northern fill slope from the northeastern corner facing westward. Revegetation is progressing in portions with western wheatgrass and smooth brome. However weed infestations (described below) are threatening successful revegetation.



Photos 3. View of jointed goatgrass within the northern project area. Approximately 2000 individuals observed.



Photos 4. View of the western project area from the northwestern corner facing southward.



Photos 5. View of dense Canada thistles within the western interim reclamation area. Approximately 2000 individuals observed.



Photo 6. View of reference area comprised of pinyon and juniper woodland with understory of antelope bitterbrush, big sagebrush, James galleta, and penstemon.