

Inspection Photos
Operator: Catamount Energy
API#: 067-06549
Date: 6/3/2020



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the western fill slope from the southwestern corner facing northward. Revegetation is progressing with sand dropseed, Indian ricegrass, and rubber rabbitbrush.



Photo 3. View of reference area comprised of pinyon and juniper woodland with understory of antelope bitterbrush, big sagebrush, James galleta, and penstemon.