

Inspection Photos

API: 05-071-60013

Operator: EP ENERGY

Inspection Date: 6/3/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-60013 | Date: 6/3/2020

Inspection Photos



Photo 1. Facing northeast along the road toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-60013 | Date: 6/3/2020

Inspection Photos



Photo 2. Facing east toward the location. The vegetation is well established at the location. The road continues past the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-60013 | Date: 6/3/2020

Inspection Photos



Photo 3. Facing south toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-60013 | Date: 6/3/2020

Inspection Photos



Photo 4. There were a few remnants of debris found at the location. It appears the unused pvc pipe previously observed has been removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-071-60013 | Date: 6/3/2020